

BK42 - Pg 70
CR 4553


CORNER RECORD

Document Number

City of OAKLAND

County of ALAMEDA, California

Brief Legal Description MACARTHUR BLVD. AND M.L.K. JR. WAY



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☐
Rancho ☐ Other ☒
Date of Survey 5/20/2011

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND BRASS DISK IN MONUMENT WELL (7/C-R/8 PER MON. MAP 285)
SEE REVERSE FOR LOCATION.
IN COMPLIANCE WITH SECTION 8771 OF THE PROFESSIONAL LAND
SURVEYORS ACT, THIS CORNER RECORD IS BEING FILED TO ESTABLISH
THE POSITION OF AN EXISTING MONUMENT PRIOR TO STREET RECONSTRUCTION.

A description of the physical condition of the monument as found and as set or reset:

SET CUT CROSSES FOR REFERENCE POINTS
SEE REVERSE FOR LOCATION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on AUG. 6 2011

Signed Denise D. Baker P.L.S or R.C.E. No. LS 7947



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 6-22-2011

and examined and filed 12-14-2011

Signed Russell R. Penland P.L.S or R.C.E. No. 5726

Title COUNTY SURVEYOR

County Surveyor's Comment



EA84Q3



M.L.K. JR. WAY

MACARTHUR
BLVD.

AT BACK
OF WALK

AT BACK
OF WALK

S26°06'25"E
129.15'

N38°49'55"E
112.77'

DISK IN MONUMENT WELL
WITH PUNCH
(7/C-R/8 PER MON. MAP 285)

S87°01'58"E
72.19'

S68°11'04"E
29.17'

AT BACK
OF WALK

IN WALK

- FOUND MONUMENT, AS NOTED
- ▲ SET CUT CROSS, AS NOTED

Prepared by:
CONSTRUCTION SURVEY, INC.
1667 TACOMA AVE.
BERKELEY, CA 94707

SCALE: 1"=30'
JOB NO. 10502
AUG. 6, 2011