


CORNER RECORD

BK 90 PG 32City of OaklandDocument Number CR 9547County of Alameda, CaliforniaBrief Legal Description City of Oakland Monument 19NW40**CORNER TYPE**

Government Corner	<input type="checkbox"/>	Control	<input type="checkbox"/>
Meander	<input type="checkbox"/>	Property	<input type="checkbox"/>
Rancho	<input type="checkbox"/>	Other	<input checked="" type="checkbox"/>

Date of Survey December 20, 2016**COORDINATES(Optional)**

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NADV88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Found iron pin in monument well located with the intersection of Elmwood Avenue and Fruitvale Avenue as shown on monument index map 109 and 121. In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner is being filed to ESTABLISH the position of an existing monument PRIOR to street or highway construction.

A description of the physical condition of the monument as found and as set or reset:

Monument found in good condition. See sketch on back

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on January 23, 2017.

Signed Michael A. Valdivia P.L.S. or R.C.E. No.: 9211**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received 12-23, 2016 and examined and filed 01-24, 2017.

Signed Albert Jordan P.L.S. or R.C.E. No.: 6623Title Deputy County Surveyor

County Surveyor's Comment _____



LEGEND

- ⊙ FOUND CITY OF OAKLAND
IRON PIN IN MONUMENT WELL
- + SET CUT CROSS
- ⊕ FD CUT CROSS PER CR5281
- FD RR SPIKE
- ALAMEDA COUNTY MONUMENT ID.

