

RECORD OF SURVEY NO. 31-45


SHEET 5 OF 9

SECTIONS 21/22/27/28, TOWNSHIP 7 NORTH, RANGE 23 EAST, M.D.B. & M.

PM 99.9 1987
CALTRANS ALUMINUM CAP
ON 1" IRON PIPE, DOWN
0.3', 3.0' EAST OF
MONUMENT POST AND
PADDLE, 55.5' WEST
OF CENTERLINE.
N. 109,540.387
E. 99,759.030

SECTION 21

SECTION 22



RESET COR SECS 21/22/27/28
ORIGINAL BLM BRASS CAP
DESTROYED DURING 1999 FLOOD.
SET CALTRANS BRASS CAP ON
2 1/2" O.D.I.P.
N. 108,766.150
E. 100,279.776


NOTE: POINT RESET BY COORDINATES.
COORDINATES THAT WERE USED TO
RESET NEW CORNER WERE PREVIOUSLY
COLLECTED IN A CALTRANS SURVEY
PRIOR TO ORIGINAL CORNER BEING
LOST IN 1999 FLOOD.

SECTION 27

SECTION 28

LEGEND:

- FOUND CALTRANS "C" MONUMENT
- CALCULATED POSITION
- ⊙ SET 3/4" REBAR W/CALTRANS ALUMINUM CAP STAMPED
"R/W 2005" WITH EITHER "BC, EC, POC, OR AP"
- FOUND MONUMENT AS NOTED
- ◆ FOUND LAND NET CORNER AS NOTED



ONE INCH EQUALS 100 FEET
CGF = 0.9997017