


CORNER RECORD

BK 53 PG 30

APN No. _____ (Optional) Document Number CR 5658
 City of BERKELEY County of ALAMEDA, California
 Brief Legal Description CUT CROSS AT THE INTERSECTION OF OXFORD STREET AND CENTER STREET



CORNER TYPE

Government Corner ☐ Control ☒
 Meander ☐ Property ☐
 Rancho ☐ Other ☐
 Date of Survey MAY 11, 2013

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to
 ESTABLISH X / REESTABLISH _____ the position of an existing monument PRIOR X / SUBSEQUENT _____
 to street or highway reconstruction. (Use this portion only when applicable.)

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
REFERENCED EXISTING CUT CROSS AT RISK OF BEING DISTURBED DURING
AN UPCOMING CONSTRUCTION PROJECT.

A description of the physical condition of the monument as found and as set or reset: _____
FOUND CUT CROSS IN GOOD CONDITION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on 16 AUGUST 2013

Signed [Signature] L.S. Number 6868

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 6-12-2013 and examined

and filed 8-26-2013

Signed [Signature] Title: County Surveyor

County Surveyor's Comment _____

